

Addendum B - List of Survey Sites

Sec-tor	Site #	Land Use	Location	Type of Problem	Recommendation	Impact	Cost
1	1	Residential	12 Totte Road	Surface sheet erosion and bare soil	Install runoff diverter, mulch	Low	low
1	2	Boat Access	left of 13 Totte Road	Sheet and rill surface shoreline erosion, bare soil	Add new surface material, gravel or pave, rubber razor	Medium	medium
1	3	Residential	23 Totte Road	Sheet & gully erosion, bare soil, delta in lake, no shoreline vegetation, shoreline erosion	Add new gravel, pave, install catchbasin, rubber razor blade	High	high
1	4	Residential	5 Treasure Island Road	Sheet and rill surface erosion, bare soil	Install infiltration steps, runoff diverter, mulch and establish buffer, reseed thinning grass	Medium	medium
1	5	Residential	35 Totte Road	Sheet and rill surface erosion, bare soil, undercut shoreline, lack of vegetation, shoreline erosion	Mulch, establish buffer, retaining wall	Low	medium
1	6	Driveway	37 Totte Road	Sheet and rill surface erosion, bare soil, inadequate shoreline vegetation	Build up with new gravel, add rubber razor, mulch and retention swales	Medium	medium
1	7	Residential	71 Totte Road	Gully erosion, shoreline is undercut	Install catch basin, roof dripline, add to buffer	Medium	medium
1	8	Private Road	Totte Rd - Utility Pole J2	Steep rock wall failure	Replace wall, remove debris and sediment	Low	low
1	9	Private Road	Totte Road Utility Pole #5	Ditch/shoulder rill and gully erosion	Add new gravel, runoff diverters, perhaps tunouts	Low	medium
1	10	Town Road	Corner of 18th & Goose Pnd Rd Pole #J4-57 to Utility pole #7	Culvert clogged	Remove clog, plunge pool, remove debris, and sediment pools.	Medium	medium
2	1	Residential	66 Point Road	Rill surface erosion and bare soil	define foot path, install runoff diverter, mulch, add to buffer, reseed thinning grass	Medium	medium
2	2	Boat Access	55 Point Road(private boat launch)	Gully erosion	Reshape and crown, slope to vegetation, install diverter	High	medium
2	3	Private Road	Point Rd between #66 & #46	Gravel road with gully erosion	add new surface material, reshape, diverters, add to buffer	Medium	medium
2	4	Residential	54 Point Road	Sheet erosion, bare soil roof runoff, gullies	add new surface material drywell at gutter downspout, mulch, rain garden	Medium	medium

Sec- tor	Site #	Land Use	Location	Type of Problem	Recommendation	Impact	Cost
2	5	Residential	6 Burlington Way	Rill surface erosion, bare soil, lack of shoreline vegetation and erosion	define access for boats and walking paths, waterbars, mulch, add to buffer	Medium	low
2	6	Residential	8 Burlington Way	Gully erosion, bare soil, roof dripline, undercutting at shoreline and lack of vegetation	remove two trees - define foot path, roof dripline, mulch, add to buffer	High	medium
2	7	Private Road	Burlington Way	Gully erosion on gravel road, hand cut ditches	Road to be redone per R, Eagleston; add gravel, reshape, crown, install catch basin, diverters, mulch and road is too wide	High	high
2	8	Residential	10 Burlington Way	Gully erosion and road shoulder gully erosion; shoreline erosion, unstable access and inadequate shoreline vegetation, old footpath directs h2o to lake	add new surface material, define foot path install infiltration steps, roof dripline, mulch and add to buffer	High	medium
2	9	Driveway	10 Burlington Way	Gully erosion bare soil, sheet flow	Add new surface material; reshape; crown, catch basin, RRB, install turnouts ditches, mulch	High	high
2	10	Residential	46 Point Road	Rill erosion, bare soil, shoreline erosion and lack of vegetation	Establish buffer, mulch	Medium	medium
2	11	Residential	44 Point Road	Gully erosion, bare soil, inadequate shoreline vegetation - former ML project; dripline is paved	define foot path, infiltration steps, drywell, rain barrel, mulch and add to buffer	High	medium
2	12	Residential	40 Point Road	Bare soil, lack of shoreline vegetation	define foot path, mulch add to buffer	High	medium
2	13	Boat Access		Rill erosion on shoulders	pave and remove broken pavement; catch basin, rubber razor blade, add to buffer	High	high
2	14	Private Road	36 Point Road	Gully erosion, culvert undersized, clogged, winter sand build up, catch basin full	add new surface material, reshape, broad based dip, open top culvert, RRB, remove debris from ditchline,	Medium	medium
2	15	Residential	36 Point Road	Gully erosion, bare soil, shoreline erosion	define foot path, infiltration steps, roof dripline, water bar, mulch and add to buffer	High	medium
2	16	Residential	30 Point Road	Bare soil at new dock footing	infiltration steps, rain barrel, mulch	Low	low
2	17	Private Road	21st street	Gully erosion, undersized ditch, shoulder erosion on paved & gravel road	reshape ditch; install tunrounts, remove debris, add gravel, reshape, crown, catch basin, broad based dip, diverters	High	high
2	18	Residential	3 Buccaneers Way	Gully erosion, bare soil, concrete ramp goes to lake	define footpath, waterbar, reshape, catch basin, mulch, no raking, reseed thinning areas	High	medium

Sec-tor	Site #	Land Use	Location	Type of Problem	Recommendation	Impact	Cost
2	19	Driveway	5 Buccaneers Way	Gully erosion, roof runoff, shoulder erosion	reshape, crown, catch basin, diverter, drywell, rain barrel, establish buffer, reseed bare areas	High	medium
2	20	Residential	7 Buccaneers Way	Gully erosion, roof runoff	roof dripline	Medium	low
3	1	Beach Access	159 23rd Street	Sheet erosion, bare soil, unstable access, lack of shoreline vegetation	Increase vegetation and add mulch	Low	low
3	2	Beach Access	18 Coffin Street	Rill & Sheet erosion, tire ruts, roof runoff and unstable shoreline access	mulch path by water, no raking, roof dripline trench, build up berm in front of house	Medium	low
3	3	Driveway	18 Coffin Street	Rill erosion, gravel-bare soil, channelized flow to lake	Add new surface material, install wtr diverters, broad base dip, mulch and resurface driveway in front of shed	Medium	medium
3	4	Trail/Path	169 23rd Street Loop	Sheet erosion, roof runoff and undercut shoreline	Install infiltration steps, runoff diverter, mulch, stabilize eroding bank, retaining wall, and vegetation and mulch	Medium	low
3	5	Driveway	173 23rd Street	Rill erosion and links to site 3-6	Define foot path, install rain garden, detention basis, define parking area and walking path	Medium	medium
3	6	Beach Access	173 23rd Street	Rill erosion, bare soil, roof runoff	stabilize foot path, infiltration steps, roof dripline trench, mulch heavily, add to buffer and no raking	Medium	medium
3	7	Residential	285 23rd Street	Surface erosion, bank failure, undercut shoreline, retaining wall failure	Repair wall,, mulch, water diverter, mulch	High	high
3	8	Residential	185 23rd Street	Sheet erosion, bare soil, roof runoff, inadequate shoreline vegetation	Extend roof dripline, mulch, build up rock wall by stairs, add to buffer, no raking and reseed thin and bare soil area.	Low	low
3	9	Driveway	187 23rd Street	Gully erosion on gravel driveway (impacted by road runoff)	Install check dams, ditch needs maintenance, runoff diverter into a rain garden	Medium	medium
3	10	Residential	187 23rd Street	Sheet erosion, bare soil, roof runoff. Kitty litter	Stabilize foot path, roof dripline, drywell at gutter downspout, mulch	Low	low
3	11	Trail/Path	5 Stern Way	Sheet erosion, bare soil, roof runoff, lack of shoreline vegetation	Infiltration steps, roof dripline, mulch, establish buffer, no raking reseed thinning grass or bare soil.	Medium	medium
3	12	Trail/Path	7 Stern Way	Bare soil and roof runoff	Install roof dripline, install mulch on original path over roots, establish buffer, no raking.	Low	low

Sec- tor	Site #	Land Use	Location	Type of Problem	Recommendation	Impact	Cost
3	1	Driveway	11 Stern Way	Grave/paved driveway with bare soil	Define driveway, add mulch and no raking	Medium	medi-
3	1	Residential	15-19 Stern Way	Bare soil and roof runoff	Roof dripline trench, mulch, no raking	Low	low
3	1	Residential	255 23rd Street	Sheet erosion, bare soil, roof runoff, de-	Clean out detention basis, install dripline, drywell at	Medium	low
3	1 6	Driveway	255 23rd Street	Gravel driveway with rill erosion, ditch has gully erosion and shoulder has gully erosion	re-define ditch, clean out basin, reshape, crown, runoff diverters, RRB,	Medium	medi- um
3	1 7	Residential	27 Long Way	Roof runoff	Stabilize area near steps by water, drywell, mulch, add to buffer, no raking	Low	low
3	1 8	Residential	39-41 Starboard	Roof runoff and start of retaining wall failure	Clean gutters, roof dripline trench, add to buffer, repair retaining wall, stabilize banking	Medium	medi- um
3	1	Residential	54 Portside	Roof runoff	Build up gravel, infiltration steps, roof dripline, mulch,	Low	medi-
3	2 0	Residential	52 Portside	Sheet erosion, roof runoff and inade- quate shoreline vegetation	Roof dripline trench, mulch, no raking	Low	low
3	2 1	Residential	50 Portside	Sheet erosion and lack of shoreline vege- tation	Roof dripline trench, mulch, add drywell	Low	low
3	2 2	Private Road	187 23rd Street Loop	Sheet and Gully surface erosion, ditch erosion, shoulder erosion, bare soil	Armor ditch, regrade, maybe install culverts and re- shape shoulders	Medium	high
3	2 3	Driveway	47 Portside	Sheet erosion, bare soil	Install catch basin, runoff diverters and mulch	Low	medi- um
3	2	Residential	12 Dance Hall Lane	Sheet erosion, bare soil and lack of	Define foot path, install infiltration trench and erosion	Low	low
3	2	Residential	27 Meader Lane	sheet erosion and bare soil	Install lots of erosion control mulch	Low	low
3	2	Residential	29 Meader Lane	sheet erosion and bare soil	Install terraces and erosion control mulch	Low	low
3	2 7	Residential	67 Katos Nose	sheet and rill erosion, bare soil and roof runoff	Install waterbar and large roof drip line	Low	low
4	1	Residential	10 Spill Way	Shoreline erosion & bank undercut	Add to buffer-blueberry exists	Low	low
4	2	Residential	10 Spill Way	Surface Erosion below concrete block	runoff diverter & buffer	Low	low
4	3	Residential	10 Spill Way	Surface erosion-bare soil-contributes 4-	ECM	Low	low
4	4	Trail/Path	Spill Way	Rill erosion-bare soil	Stabilize path-install runoff diverter	Low	medi- um
4	5	Town Road	39 26th Street	Gully erosion on gravel road	remove grader-plow berms	Medium	medi- um

Sec-tor	Site #	Land Use	Location	Type of Problem	Recommendation	Impact	Cost
4	6	Residential	38 26th Street	Sheet erosion at pipe outlet	runoff diverter/ECM	Low	low
4	7	Residential	36 26th Street	Roof runoff erosion	Roof dripline	Low	low
4	8	Residential	24 26th Street	Trail-Path bare soil	Diverter-mulch-buffer	Low	medi-um
4	9	Residential	148 Shapleigh Corner Road	Bare soil-sheet erosion	Diverter-add to buffer	Low	low
4	10	Private Road	11 Village Circle	Gravel road-rill erosion	define foot path, broad based dip, waterbar, buffer	Medium	medi-um
4	11	Town Road	Stream Crossing on 24th Street	Gravel road -culvert inlet unstable, grader berm, perched culvert, shoulder erosion	armor inlet stabilize shoulder	Low	low
4	12	Residential	11 Sunfish	Bare soil along the shoreline	runoff diverter and buffer	Medium	medi-um
4	13	Driveway	83 24th Street	Sheet erosion -failed RRB	rehab existing RRB	Low	low
4	14	Town Road	Across from 81 24th Street	Gravel road with gully erosion	Armor with riprap	Medium	medi-um
4	15	Residential	17 Hollon Way	Roof runoff erosion	Roof dripline	Low	low
4	16	Residential	21 Hollon Way	Surface sheet erosion	Establish buffer,define footpath, runoff diverter and mulch	Medium	medi-um
4	17	Driveway	36 24th St & 21 Hollon Way	Surface erosion, bare soil, plow -grader berm	remove berm, install ditch, waterbar, clean turnout	Medium	medi-um
4	18	Residential	11 Hollon Way	Roof runoff erosion	define path, roofdrip line trench, mulch, buffer	Low	low
4	19	Beach Access	Rawnsley Cove	Rill erosion on beach	waterbar, rain garden,buffer	High	medi-um
5	1	Residential	112 Shapleigh Corner Road	Rill erosion, bare soil steep sloped	drywell, mulch, establish buffer, reseed thinning grass	Low	low
5	2	Residential	94 Shapleigh Corner Road	Surface sheet erosion, bare soil, roof runoff, site under construction, blown out retaining wall and new patio	Provide info on permit requirements and BMP's during construction, define and stabilize foot path, runoff diverter, drywell at gutter downspout, mulch and establish buffer	Medium	medium
5	3	Driveway	80 Shapleigh Corner Road	Gravel driveway with rill erosion & hillside beside driveway	Armor base of hill beside driveway and stabilize slope, add new material, runoff diverters RRB.	High	medium
5	4	Town Road	Across street from 21 Shapleigh Corner Rd, next to sign with town names	Gully erosion off paved road, shoulder gully erosion, winter sand, plunge pool completely full	Clean out plunge pool.	High	low
5	5	Town Road	100 ft west of intersection of Rt 109 & 11	Steep paved-surface rill erosion and shoulder rill erosion	Maintenance needed on slope	Medium	low

Sec-	Site	Land Use	Location	Type of Problem	Recommendation	Impact	Cost
5	6	Town Road	South side of bridge over lake	Gully erosion on shoulder, winter sand	Maintenance needed on slope, redirect runoff using curbing, remove chute	Medium	medium
5	7	Boat Access	1 6th Street	Gravel surface with sheet erosion and bare soil	Install new surface material at least 1.5" crushed, RRB, mulch	Medium	medium
5	8	Residential	8 Abenaki Way	Bare soil, roof runoff, shoreline erosion and unstable access	Install infiltration steps, roof dripline trench, rain barrel	Low	low
5	9	Residential	15 5th Street	Sheet erosion and bare soil	roof dripline, mulch	Medium	low
5	10	Driveway	32 5th Street	Rill erosion on gravel driveway	Add new surface material, crown, RRB and mulch	High	low
5	11	Driveway	17 5th Street	Sheet erosion on moderate slope	install waterbar, and roof dripline trench	Medium	low
5	12	Residential	19 5th Street	Sheet erosion and bare soil	Drywell at gutter downspout, clean out RRB, mulch, and no raking	Medium	low
5	13	Driveway	4 4th Street	Gully surface erosion, undersized culvert, rill erosion on moderate slope with direct flow to lake	Remove clog in culvert and enlarge, clean out ditch line all the way to lake	High	medium
5	14	Town Road	3rd Street & Route 11	Surface gully erosion and ditch gully erosion	Install culvert, ditch, new surface material, recycled asphalt, and reshape crown	High	medium
5	15	Driveway	17 3rd Street	Surface sheet and rill erosion	Add new surface material, reshape crown and infiltration trench	Medium	medium
5	16	Residential	17 3rd Street	Bare soil and shoreline erosion	Install drywell at foundation drain, roof dripline, add crushed stone under outdoor shower and establish buffer just below outdoor shower	Medium	low
5	17	Boat Access	Mousam Lake Boat Launch	Gravel road shoulder erosion	add crushed stone on shoulders or reclaimed asphalt, replace launch blocks	High	high
6	1	Residential	36 Old Loop Road	Sheet erosion, bare soil shoreline erosion	Roof dripline, mulch, establish buffer	Low	low
6	2	Residential	38 Old Loop Road	Sheet erosion, inadequate shoreline vegetation and shoreline erosion	Roof dripline, mulch	Low	low
6	3	Residential	46 Old Loop Road	Sheet erosion, bare soil lack of shoreline vegetation	roof dripline, mulch and establish buffer	Low	low
6	4	Residential	54 Old Loop Road	Rill and Sheet erosion, bare soil	Waterbar, establish buffer, rain garden and mulch	Low	low
6	5	Residential	59 Old Loop Road	Sheet and rill erosion, bare soil and inadequate shoreline vegetation	Waterbars, mulch, retention swale, establish buffer	High	medium
6	6	Boat Access	65 Old Loop Road	Sheet and rill erosion, bare soil and shoreline erosion	Mulch, establish buffer, stabilize area	Low	low
6	7	Residential	112 30th Street	Sheet erosion and bare soil	Add mulch, establish buffer	Low	low
6	8	Residential	108 30th Street	Bare soil, inadequate shoreline vegetation	Mulch, and retention swales	Low	low

Sec- tor	Site #	Land Use	Location	Type of Problem	Recommendation	Impact	Cost
6	9	Residential	122 30th Street	Sheet erosion and bare soil	Drywell at gutter downspout, and mulch	Low	low
6	10	Driveway	128 30th Street	Gravel driveway with gully and rill erosion, bare soil	Add new surface material, infiltration steps, drywell, runoff diverter, mulch and add buffer	Medium	medium
6	11	Private Road	170 30th Street	Sheet and rill erosion, bare soil	Add gravel, vegetate shoulder, install runoff diverter and sediment basin	High	medium
6	12	Residential	31st Street	Sheet erosion and bare soil	mulch	Low	low
6	13	Residential	37 Cattail Loop	Sheet erosion and bare soil, lack of shoreline vegetation	Install runoff diverter, mulch and reseed thinning patches of grass	Low	low
6	14	Residential	156 31st Street	Sheet erosion bare soil	Mulch bare soil	Low	low
6	15	Town Road	Stream Crossing on Lebanon Rd, just past Jenni Kate Ln	Unstable inlet and outlet, with shoulder erosion	Armor inlet and outlet and may need to be lengthened	Medium	medium
6	16	Town Road	Murray Road @ Lebanon Rd	Paved town road, lack of ditching	Shoulder excessive pile of gravel on shoulder/ditch	Low	low
6	17	Town Road	Murray Road at stream crossing	Gravel road with shoulder erosion		Low	low
7	1	Residential	43 32nd Street	Shoreline erosion, bare soil	Establish buffer, install riprap	Low	low
7	2	Residential	63 32nd Street	Rill erosion, bare soil, roof runoff, lack of shoreline vegetation	Define & stabilize foot path, mulch and add to buffer	Low	low
7	3	Private Road	32nd Street-between #77 & #103	Gravel Rd, rill erosion, clogged & undersized culvert, plow material near water-evidence of road washouts due to clogged culvert	Remove clog, enlarge culvert and install plunge pool, stabilize snow plow banks at water edge	Medium	high
7	4	Driveway	108 32nd street	Gravel driveway, bare soil and no shoreline vegetation	mulch over bare soil, establish buffer near waterbar	Medium	low
7	5	Residential	32nd Street	Bare soil, rill erosion, lack of shoreline vegetation	Reset timber diverter, mulch and establish buffer	Medium	low
7	6	ROW	32nd Street	Right of way - Rill erosion, bare soil	Clean and reset terraces, add a timber near RRB and mulch	High	medium
7	7	Residential	204 32nd Street	Rill & sheet erosion, bare soil, lack of shoreline vegetation, retaining wall failing	mulch, establish buffer, replace retaining wall, neighbor impact	High	high

Sec- tor	Site #	Land Use	Location	Type of Problem	Recommendation	Impact	Cost
7	8	Construction	33rd Street	Sheet and rill erosion, bare soil	Silt fence-ECM berms	Low	low
7	9	Residential	34th Street	Bare soil, rill erosion	Reshape-reclaim berm to divert towards garage, rubber razor blade, add to buffer	High	medium
7	10	Residential	220 34th Street	Rill erosion, bare soil and lack of shoreline vegetation	Install drywell at gutter downspout, gutters, mulch, establish buffer and terracing	Medium	medium
7	11	Boat Access	ROW 34th Street	Rill & gully erosion, unstable access	Install recycled asphalt or pave, rubber razor, dig out ?? Area left side of ROW	High	medium
7	12	Residential	250 34th Street	Sheet erosion and bare soil	Define and stabilize foot path, mulch, needs wheelchair access perhaps infiltration pavers	Low	low
8	1	Commercial	Acton Trading Post	All impervious cover, no infiltration of any runoff from property	Develop spill plan, ways to install stormwater treatments	High	high
8	2	State Road	Route 109-No of Trading Post	Surface erosion with shoulder rill erosion	Meander foot path, define path, stabilize	Medium	medium
8	3	Trail/Path	Route 109 - West side - behind Acton Trading Post	Surface has gully erosion, ditch erosion and shoulder erosion, lack of shoreline vegetation, unstable access to shoreline	Install turnouts, stabilize foot path and install diverters	High	medium
8	4	Residential	51 Tanzella Drive	Sheet erosion, bare soil and inadequate shoreline vegetation	Add to buffer, no raking and add mulch	Medium	low
8	5	Driveway	45 Tanzella Drive	Gravel driveway, rill erosion and bare soil - runoff from driveway to private road to lake	Install runoff diverters, RRB, roof drip line trench	Medium	low
8	6	Beach Access	31 Tanzella Drive	Rill erosion on surface and shoulder, inadequate shoreline vegetation	Vegetate shoulder, define foot path and add to buffer	Medium	low
8	7	Beach Access	270 7th Street	Rill surface and shoulder erosion and lack of shoreline vegetation	Vegetate shoulder, define foot path and add to buffer	Medium	low
8	8	Residential	229 7th Street	Driveway paved but drains into conduit and empties into lake	filter driveway runoff at base of driveway, reduce fertilizer usage	Medium	medium
8	9	Residential	213 7th Street	Surface and ditch gully erosion, bare soil, shoreline erosion-erosion along edge of steep paved driveway	add crushed stone at edge of driveway and no raking	Medium	low
8	10	Residential	177 7th Street	Rill and gully surface erosion-abuts a small stream	Install infiltration steps, roof dripline trench and ECM	High	low
8	11	Residential	171 7th Street	Gully surface erosion, crushed culvert, ditch rill erosion on steep slope	Replace culvert, install catch basin, establish buffer, need discussion with landowner regarding lawn maintenance and bmp's	High	medium

Sec-tor	Site #	Land Use	Location	Type of Problem	Recommendation	Impact	Cost
8	12	Driveway	161 7th Street	Paved - gully erosion	Crushed stone trench at base of paved driveway	Medium	low
8	13	Residential	87 7th Street	Gully surface erosion, bare soil, inadequate shoreline vegetation and shoreline erosion	Install infiltration steps and a runoff diverter. YCC project?	Medium	low
8	14	Driveway	67 7th Street	Bare soil from raking, gully surface erosion	Install runoff diverters, mulch and no raking. YCC project?	Medium	low
8	15	Trail/Path		Gully erosion, bare soil and unstable access	Install runoff diverters, define path, mulch. YCC project?	High	low
8	16	Residential	30 Triangle Street	Surface sheet erosion and bare soil	Install runoff diverter, mulch, rain garden, establish buffer	Medium	low
8	17	Residential	104 10th Street	Shoreline erosion retaining wall ready to fail	Replace retaining wall soon	Medium	high
8	18	Residential	132 10th Street	Surface sheet erosion and bare soil	mulch and add vegetation	Low	low
8	19	Boat Access	76 10th Street	Rill and gully surface erosion, shoreline erosion	Paved driveway runoff causing erosion onto beach access	High	medium
9	1	Residential	33 Aspen Lane	Sheet erosion, delta in lake, bare soil, lack of shoreline erosion	Stabilize foot path, establish buffer	Low	low
9	2	Residential	31 Aspen Lane	Delta in lake, lack of shoreline vegetation and unstable accessq	define path, roof dripline trench, establish buffer	Medium	low
9	3	Town Road	Aspen Lane	Rill erosion on gravel road, lack of ditching, shoulder erosion and bank undercut	Install ditch, new surface material, reshape	High	high
9	4	Residential	19 Aspen Lane	Steep slope, rill erosion, lack of shoreline vegetation	Install runoff diverter, mulch and establish buffer	Medium	medium
9	5	Residential	3 Aspen Lane	Steep slope, lack of shoreline vegetation and shoreline erosion	Install diverter, mulch and establish buffer	Medium	medium
9	6	Residential	11 Aspen Lane	Sheet erosion, bare soil, delta in lake inadequate shoreline vegetation	define foot path, mulch, add to buffer	Low	low
9	7	Town Road	Aspen Lane or 12th Street?	Sheet and rill erosion, delta in lake, lack of shoreline vegetation, shoreline erosion and unstable access	Define foot path, install diverter, mulch and establish buffer	High	medium
9	8	Residential	130 12th Street	Sheet erosion, inadequate shoreline vegetation and unstable access	define foot path, mulch, add to buffer	Medium	low

Sec- tor	Site #	Land Use	Location	Type of Problem	Recommendation	Impact	Cost
9	9	Residential	160 12th Street	Sheet erosion, lack of shoreline vegetation and compacted path	add new crushed stone and dig deeper, install run-off diverter	Low	low
9	10	Residential	125 Avenue A	Sheet erosion, bare soil	add mulch and vegetation	Low	low
9	11	Residential	113 Avenue A	Bare soil	define foot path and add mulch	Low	medium
9	12	Residential	97 Avenue A	Bare soil	mulch and add vegetation	Low	low
9	13	Residential	43 Avenue A	Sheet erosion, lack of shoreline vegetation and unstable access	Establish buffer and add mulch	Medium	low
9	14	Residential	44 Hemlock	Lack of shoreline vegetation	Install roof dripline trench, establish buffer, add crushed stone under deck	Medium	medium
9	15	Residential	48 Hemlock	Lack of shoreline vegetation and bare soil	Install roof dripline trench, infiltration trench, establish buffer	Medium	medium
9	16	Residential	58 Hemlock	Lack of vegetation	Add vegetation to steep hill	Medium	medium
9	17	Residential	19 Lilac	Sheet erosion, lack of shoreline vegetation	Add to buffer	Low	low
9	18	Residential	39 Avenue B	Unstable access	Stabilize foot path	Low	low
9	19	Residential	15 Hickory Lane	Sheet erosion & bare soil	Establish buffer and add mulch	Medium	low
9	20	Residential	3 Hickory Lane	Sheet erosion and bare soil	Install roof dripline, mulch	Low	low
9	21	Residential	25 Avenue C	Bare soil	Install roof dripline	Low	low
9	22	Driveway	182 and 184 Avenue D	Rill erosion on gravel driveway, moderate slope, RRB needs to be reset	Build up with new gravel, reshape and crown, reset RRB	Medium	medium
10	1	Residential	156 Covewood Road	Surface sheet erosion	Buildup driveway, vegetate shoulder, add waterbar	Low	low
10	2	Residential	150 Covewood Road	Surface sheet and rill erosion on a moderate slope	Mulch	Low	low
10	3	Residential	90 Covewood Road	Moderate slope sheet erosion	add water bar and ECM	Low	low
10	4	Residential	19 Avenue G	Steep slope with rill erosion	Define foot path with infiltration steps and ECM	Medium	low
10	5	Residential	27 Avenue G	Steep slope with rill erosion	define and stabilize foot path and add mulch, waterbar	Medium	medium
10	6	Residential	676 13th Street	Steep slope with shoreline erosion-failing retaining wall	Replace/repair retaining wall	High	high
10	7	Residential	704 13th Street	Steep slope-failing retaining wall, shoreline erosion	Repair retaining wall	High	high
10	8	Residential	52 Avenue F	Steep slope, surface erosion and roof runoff	Install roof dripline trench, runoff diverter, and ECM	Low	low

Sec- tor	Site #	Land Use	Location	Type of Problem	Recommendation	Impact	Cost
10	9	Residential	580 13th Street	Steep slope with potential failing retaining wall	Repair or replace retaining wall & add to buffer	Medium	high
10	10	Residential	774 13th Street	Moderate slope sheet erosion	add infiltration trench at head of stairs, clean out RRB and plunge pool	Low	low
10	11	Residential	19 Avenue H	Moderate slope sheet erosion	Clean out infiltration steps ECM, rain garden, establish buffer	Low	low
11	1	ROW	14th Street ROW	ROW with sheet and rill erosion, inadequate shoreline vegetation	Install water diverters and mulch	Medium	low
11	2	Residential	Acorn street	Sheet and rill surface erosion with bare soil undercut shoreline, lack of vegetation, unstable access and erosion	Install infiltration steps, waterbar, roof dripline, mulch, buffer and reseed bare soil	High	medium
11	3	Residential	Crook Neck Way	Sheet erosion and bare soil. shoreline erosion.	Install infiltration steps, waterbar, raingarden and add to buffer	Low	low
11	4	Residential	167 14th Street	Shoreline undercut, erosion and inadequate shoreline vegetation	Establish buffer, mulch and coconut roll	Medium	medium
11	5	Residential	193 14th Street	Sheet erosion and bare soil	establish buffer, install waterbar and mulch	Low	low
11	6	Private Road	End of 14th Street	Gully erosion, shoulder erosion,	replace culvert and stabilize inlet and outlet	Medium	medium
11	7	Private Road	30 Sachem's Way	Sheet and rill erosion, lack of shoreline vegetation	runoff diverter, infiltration steps, mulch, establish buffer	High	medium
11	8	Private Road	31 Sachem's Way	Sheet and rill erosion	pave, vegetate shoulder, install catch basin, and or rubber razoe	Medium	medium
11	9	Residential	364 16th Street Loop	Sheet and rill erosion, bare soil and shoreline erosion	drywell and gutter downspout, mulch and waterbar	Low	low
11	10	Residential	9 Narrows Lane	Failed retaining wall and lack of vegetation at shoreline	Replace retaining wall; cover bare soil with mulch, plant buffer	High	high
11	11	Private Road	Narrows Lane	Sheet erosion, steep, lack of ditches	add new surface material, instal rubber razor blades, reshape,vegetate	Medium	medium
11	12	Private Road	16th street above Narrows Lane	Sheet erosion, shoulder erosion	add turn out, stabilize, new surface material	Medium	medium
12	1	Town Road	Nason Road, Acton	Unstable inlet and outlet of culvert	lengthen and armor inlet and outlet	Medium	medium
12	2	Town Road	H Road east of Town Hall	Ditch and road shoulder gully erosion	Install ditch, armor with stone, or use recycled asphalt	High	medium
12	3	Town Road	160 Sanborn Road	Culvert outlet perched (at dam)	Re-set culvert, armor and install plunge pool	Medium	medium